## National Transportation Safety Board FACTUAL REPERT

NTSB ID: DEN05MA029 Aircraft Registration Number: N873G

Occurrence Date: 11/28/2004 Most Critical Injury: Fatal

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Nearest City/Place	State	Zip Code	Local Time	Time Zone	
Montrose	СО	81402	0955	MST	
Airport Proximity: Off Airport/Airstrip	Distance From	m Landing Facility:	0.5	Direction Fro	m Airport:

Aircraft Information Summary

Alicial illioillation Sullinary		
Aircraft Manufacturer	Model/Series	Type of Aircraft
Canadair	CL-600-2A12	Airplane

Sightseeing Flight: No Air Medical Transport Flight: No

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On November 28, 2004, about 0958 mountain standard time, a Canadair, Ltd., CL-600-2A12, N873G, registered to Hop-a-Jet, Inc., and operated by Air Castle Corporation dba Global Aviation as Glo-Air flight 73, collided with the ground during takeoff at Montrose Regional Airport (MTJ), Montrose, Colorado. The on-demand charter flight was operated under the provisions of 14 Code of Federal Regulations (CFR) Part 135 on an instrument flight rules (IFR) flight plan. Instrument meteorological conditions prevailed, and snow was falling. Of the six occupants on board, the captain, the flight attendant, and one passenger were killed, and the first officer and two passengers were seriously injured. The airplane was destroyed by impact forces and postcrash fire. The flight was en route to South Bend Regional Airport (SBN), South Bend, Indiana.

The complete report of this accident investigation was adopted by the Safety Board on May 2, 2006, and is available on: http://www.ntsb.gov/publictn/2006/AAB0603.pdf

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN05MA029

Occurrence Date: 11/28/2004

AVIATION	rrence Type	e: Accider										
Landing Facility/Approach In	formation	•					•					
Airport Name			Airport ID:	Airport	Elevation	Rur	nway Used	Runwa	Runway Length		Runw	vay Width
Montrose Regional			MTJ	57	59 Ft. MSL	. 31		7500	00 10		100	
Runway Surface Type: Asphalt												
Runway Surface Condition: Slush	covered											
Type Instrument Approach: Unknown	own											
VFR Approach/Landing: Unknown	ำ											
Aircraft Information												
Aircraft Manufacturer Canadair				el/Series 600-2A12					Serial 3009	Number		
Airworthiness Certificate(s): Trans	sport		•						•			
Landing Gear Type: Retractable	- Tricycle											
Homebuilt Aircraft? No	Number of Seats:	13	Certific	ed Max Gr	oss Wt.		44600 LBS Numbe			er of Engines: 2		2
Engine Type: Turbo Fan			_	Engine Manufacturer: Model/Series: CF34-3A2						Rated Power: 8729 LBS		
- Aircraft Inspection Information												
Type of Last Inspection			Date of La	Date of Last Inspection Time Sir				ince Last Inspection			e Tot	tal Time
Continuous Airworthiness			11/2004	11/2004					14316.6 Hours			
- Emergency Locator Transmitter (	ELT) Information											
ELT Installed? Yes	ELT Operate	ed? Ye	s		EL <sup>-</sup>	Γ Aided	in Locating A	ccident S	Site? No	)		
Owner/Operator Information												
Registered Aircraft Owner			Street	Address 534	0 NW 21s	t Ave I	Hangar 60					
Hop-A-Jet Incorporated			City	I :								Zip Code
			Ft. Lauderdale Street Address									333092722
Operator of Aircraft			Street		nunderbol	t Drive						
Air Castle Corporation			City	City							;	Zip Code
Operator Does Business As: Hop-	A lot Incorporate			Millville Operator Designator Code: YQC								08332
- Type of U.S. Certificate(s) Held: I		<u>u</u>					perator besig	inator ot	Juc. 1 Q	!CA		
Air Carrier Operating Certificate(s)												
Operating Certificate:				Oper	ator Certifi	cate:						
Regulation Flight Conducted Unde	r: Part 135: Air Ta	ıxi & Co	ommuter									
Type of Flight Operation Conducted	d: Non-scheduled	; Dome	stic; Pass	enger On	ly							
		FACTU	J <b>AL REP</b> (	ORT - AV	'IATION							Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN05MA029

Occurrence Date: 11/28/2004

	Occurrence Type: Accident														
First Pilot Inf	ormation								•						
Name						City					tate	Date of Birth	Age		
On File						On File	le On Fil					On File	50		
Sex: M Se	at Occupied:	Left	Prir	ncipal Profes	sion: Occup	ational	nal Pilot Certificate Number: On File								
Certificate(s):	Airlin	e Transpor	t; Commerc	ial											
Airplane Rating	Airplane Rating(s): Multi-engine Land; Single-engine Land														
Rotorcraft/Glider/LTA: Helicopter															
Instrument Rating(s): Airplane															
Instructor Ratin	g(s):														
Type Rating/Endorsement for Accident/Incident Aircraft? Yes  Current Biennial Flight Review? 06/2004															
Medical Cert.: Class 1 Medical Cert. Status: Valid Medicalw/ waivers/lim. Date of Last Medical Exam: 11/2004											14				
		<u> </u>													
- Flight Time M	atrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night		Ins Actual	trument Simulat	ed	Rotorcraft	Glider	Lighter Than Air		
Total Time		12396	913	5257	6299		865	188		150					
Pilot In Comman	d(PIC)	10851	828		5268										
Instructor															
Last 90 Days		165	165	165			40								
Last 30 Days		87	87	87			20								
Last 24 Hours		2	2		2		0								
Seatbelt Used?	Yes	Shou	lder Harness	Used? Yes		Т	oxico	logy Perfo	rmed? Ye	es	S	Second Pilot?	Yes		
Flight Plan/Iti	inerary														
Type of Flight P		R													
Departure Point	t						State Airport Identifi		ifier	er Departure 1		Time Zone			
Montrose							CO MTJ			1055	5	MST			
Destination							State	Ai	port Ident	ifier					
South Bend						ı	IN SBN								
Type of Clearar	nce: IFR														
Type of Airspac	e:														
Weather Info	rmation														
Source of Brief		Comica Ct-	tion												
	Flight 8	Service Stat	uon												
Method of Brief	fing: Teleph	ione													
				FACTUAL	REPORT -	- AVIA	ΓΙΟΝ	1					Page 3		

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN05MA029

Occurrence Date: 11/28/2004

Occurrence Type: Accident

	ETYBOR		Occ	urrence	: Type:	Accider	Ιτ						
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF E	Elevatio	n	WOF D	istance Fron	n Accid	dent Site		Direction From Accident Site		
MTJ	0953	MST	57	50 Ft. N	MSL				NM		Deg. Mag.		
Sky/Lowest Cloud Condition: Few 500 Ft. AGL Condition of Light: Day													
Lowest Ce	illing: Overcast		90	900 Ft. AGL Visib			ility:	1.25	SM Altimeter:			29.67	"Hg
Temperature: -1 °C Dew Point: -2 °C Wind Direction:									Density Altitude: Ft.				
Wind Spee	ed: Calm			Weather Conditions at Accident Site: Instrument Conditions									
Visibility (RVR): Ft. Visibility (RVV) SM Intensity of Precipitation: Light													
Restriction	s to Visibility:												
Type of Pre	ecipitation: Snow												
Accident	Information												
Aircraft Dar	mage: Destroyed		Aircr	aft Fire:	Grour	nd			Aircraft Expl	losio	n <b>Ground</b>		
Classificati	ion: U.S. Registered/U	.S. Soil	•										
- Injury Sui	mmary Matrix	Fatal	Serious	Minor		None	TOTAL						
First Pi	ilot	1					1						
Second	d Pilot		1				1						
Studen	nt Pilot							1					
Flight I	nstructor							1					
Check	Pilot							1					
Flight E	Engineer							]					
Cabin A	Attendants	1					1	]					
Other C	Crew												
Passen	ngers	1	2				3	]					
- TOTAL A	ABOARD -	3	3				6	]					
Other C	Ground							1					
- GRAND	O TOTAL -	3	3				6	1					
					•								

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: DEN05MA029

Occurrence Date: 11/28/2004

Occurrence Type: Accident

## Administrative Information

Investigator-In-Charge (IIC)

Arnold W. Scott

Additional Persons Participating in This Accident/Incident Investigation:

Jennifer Kaisaer

National Transportation Safety Board

Denver, CO

Christine K Soucy

Federal Avation Administration

Washington, DC

William J Hughes

Federal Aviation Administration

Salt Lake City, UT

Mark Z Rushton

Federal Aviation Administration

Salt Lake City, UT

John Heath Bombardier

W. Dorval, Canada,

Francois Pelletier

Bombardier

W. Dorval, Canada,

Leslie McVey General Electric

Howard Winkler

General Electric

Robert Johnson

Jet Alliance/Air Castle Worldwide Executive Jet Ch

Millville, NJ

Michael E Woolston

Air Castle Worldwide Executive Jet Charter

Millville, NJ

Scott Brownlee

Montrose Regional Airport

Montrose, CO

Mark Young

Montrose City/County Coroner

Montrose, CO

Mark Schelling

Montrose Police Department

Montrose, CO

Jim McMenemy Transport Canada

Ottawa, Canada,

Dan Poulin

Transport Canada

Ottawa, Canada,

David McNair

Transportation Safety Board of Canada

Edmonton, Canada,

John Pearson

Transportation Safety Board of Canada

Edmonton, Canada,

Mike Tomm

Transportation Safety Board Of Canada

Edmonton, Canada,